



GREAT NORTHERN  
POP CORN  
COMPANY

15"

12"

30"

16 <sup>7</sup>/<sub>8</sub> inch diameter



Popcorn machine measures  ~~$13\frac{3}{4}$ " deep,  $16\frac{3}{4}$ " wide~~  
 $14\frac{3}{4}$ " deep;  $17\frac{3}{4}$ " wide

floor of cart where popcorn machine will sit:  
minimum  $15$ " deep,  $19$ " wide

height of floor <sup>of cart</sup> from floor:  $30$ "

There should be a  $2$ " lip around the area where the  
p. machine sit; some way to secure the p. machine to the  
cart to prevent it tipping & falling off the cart.

The storage area ~~by~~ ~~can~~ be ~~#~~  $18$ " tall

